INDIVIDUAL PROPERTY/DISTRICT MARYLAND HISTORICAL TRUST INTERNAL NR-ELIGIBILITY REVIEW FORM

Property/District Name: <u>Samuel Hoke House</u>	Survey Number: <u>F-8-40</u>
Project: <u>MD 26 over Israel Creek</u>	Agency: <u>FHWA/SHA</u>
Site visit by MHT Staff: X no yes Name	
Eligibility recommended Eligibility not recomm	nended <u>X</u>
Criteria:AB <u>X</u> CD Considerations:AB	3CDEFGNone
Justification for decision: (Use continuation sheet if ne	ecessary and attach map)
Based on the information prepared by SHA, the Samuel Hoke of MD 26, east of Ceresville, does not meet the National Jisting due to lack of integrity. When inventoried in 1979 ory stone house and numerous domestic and agricultural or and later 19th century and strongly conveyed the sense of to the information provided by SHA, the property was allowed years before acquisition by the present owners who undertoo house, summer kitchen, and ice house. These buildings are buildings. In addition, a quarried stone fence and gatewaten removed.	Register Criteria for individual 9, the farmstead included the two utbuildings dating from the early the 19th century farm. According ed to deteriorate for a number of ok a virtual reconstruction of the hardly recognizable as historic
Documentation on the property/district is presented in:	Project file, Maryland Inventory
<u>form F-8-40</u>	
Prepared by: <u>Deborah Sheetenhelm (form)</u> , Rita Suffness (upd	
Reviewer, Office of Preservation Services	August 25, 1994
1	Date
program concurrence: yes no not applicab	ole V. Z/2:0:1
Reviewer, NR program	Date

(my

The Samuel Hoke House, a two and a half story square shaped stone structure, is located on the south side of Route 26 facing west in the village of Ceresville. The principal facade is three bays wide. Occupying the second bay is a wooden pannelled door set in a recessed panelled doorway. The entrance is crowned by a three light transom. Occupying the remaining bays are original pegged 6/6 windows crowned by wooden lintels with corner block trim. An encircling porch spans the west and north sides of the structure. It is supported by double columns with decorative brackets set in quarried stone column bases. The porch, like the structure as a whole, is covered by a standing seam tin roof. The structure rests upon a stone rubble and quarried stone foundation. Two original brick chimneys rise from the structure.

A number of significant outbuildings are found on the property. The outbuildings to the east side of the house are all constructed of coursed quarried stone. A frame bank barn and two brick silos further add distinction to this architecturally significant house. Historically the house is significant for its association with a number of prominent Frederick County residents. Built by William E. Williams in the 1820's, the lands on which the house is situated included the Ceresville Stone Quarry, source of the native stone used in the construction of the house and outbuildings, and in a number of structures in the area.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME				
HISTORIC Sa	muel Hoke House			
AND/OR COMMON				
2 LOCATION	J			
STREET & NUMBER				
South side	of Route 26 facing wes	t	CONGRESSIONAL DISTR	RICT
Ceresville	_	VICINITY OF	Sixth M 58/P	2
STATE Maryland			county Frederick	
3 CLASSIFIC	CATION			
CATEGORY	OWNERSHIP	STATUS	PRES	SENT USE
DISTRICT	PUBLIC V	XOCCUPIED	X_AGRICULTURE	MUSEUM
X_BUILDING(S)STRUCTURE	_XPRIVATE BOTH	UNOCCUPIEDWORK IN PROGRESS	COMMERCIAL EDUCATIONAL	PARK XPRIVATE RESIDENCE
SITE	PUBLIC ACQUISITION	ACCESSIBLE	ENTERTAINMENT	
OBJECT	_IN PROCESS	XYES: RESTRICTED	GOVERNMENT	SCIENTIFIC
	BEING CONSIDERED	YES: UNRESTRICTED NO	INDUSTRIAL MILITARY	TRANSPORTATIONOTHER:
4 OWNER O	F PROPERTY			
	d Mrs. Eugene Doody, J	r.	Telephone #: 66	52-8466
STREET & NUMBER			1010110 11	
707 Wyngate	Drive			
CITY TOWN Frederick		VICINITY OF		zip code 1701
	N OF LEGAL DESCR			1701
	4 OF MEGAL DECOM	11014	Liber #: 452	
COURTHOUSE. REGISTRY OF DEEDS	, _{ετς.} Frederick Cou	nty Courthouse	Folio #: 493	
STREET & NUMBER				
North Court	St.		STATE	
Frederick			Maryland	
	NTATION IN EXIST	ING SURVEYS		
TITLE	VIIIIOIVIIV EIIIOI	in o o o in v E i o		
DATE		FEDERAL	STATECOUNTYLOCA	
DEPOSITORY FOR SURVEY RECORDS				
CITY, TOWN			STATE	
 .				



F-8-40

CONDITION

CHECK ONE

CHECK ONE

_EXCELLENT

__FAIR

__DETERIORATED
__RUINS
__UNEXPOSED

XUNALTERED
_ALTERED

XORIGINAL SITE

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Samuel Hoke House, a two story square shaped stone structure, is situated on the south side of Route 26 facing west in the village of Ceresville.

The principal facade is three bays wide. Occupying the second bay is a recessed panelled doorway. The entrance is crowned by a three light transom. Occupying the remaining bays are original pegged 6/6 windows. There is evidence of shutters which once framed the windows but are now missing. The windows are crowned by wooden lintels with corner block trim.

An encircling porch spans the west and north side of the structure. The porch is supported by double wooden columns with decorative brackets. The base of these columns rests in quarried stone column bases. The porch is covered by a standing seam tin roof.

The north side of the structure is three bays wide. An entrance is located in the second bay. It consists of a wooden panelled door set in a recessed panelled doorway. A 9/6 window occupies one of the remaining two bays on the first floor. All windows are original pegged windows crowned by wooden lintels with decorative corner blocks.

The structure is covered by a standing seam tin roof. Beneath the roof is found an original boxed cornice with return. It rests upon a stone rubble and quarried stone foundation. Two original brick chimneys rise from the structure, one from the north and one from the south gable end.

A number of significant outbuildings are found on the property. The outbuildings to the east side of the house are all constructed of quarried stone, coursed with quoin work trim. One stone structure, probably used as a summer kitchen or smokehouse is found to the rear of the house. It is constructed of quarried stone with a massive quarried stone chimney and covered by a standing seam tin roof. In addition to the stone outbuildings, a frame bank barn and two brick silos are the significant farm buildings.

The house is surrounded by a quarried stone fence and gateway which lend an impressive air to a significant early nineteenth century structure. The house banked against a small hill commands a view of the surrounding meadows leading to the Monocacy River.

8 SIGNIFICANCE

F-3-4

PREHISTORIC 1400-1499	ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNINGCONSERVATION	LANDSCAPE ARCHITECTURE	RELIGION SCIENCE
_1500-1599	XAGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE
_1600-1699	X_ARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAN
_1700-1799	ART	ENGINEERING	MUSIC	THEATER
<u>X</u> 1800-1899	COMMERCE	EXPLORATION/SETTLEMENT	PHILOSOPHY	_TRANSPORTATION
_1900-	COMMUNICATIONS	XINDUSTRYINVENTION	POLITICS/GOVERNMENT	_OTHER (SPECIFY)

STATEMENT OF SIGNIFICANCE

The Samuel Hoke House, a two and a half story square shaped stone building, was built by William E. Williams in the 1820's. The land on which the house is situated was originally a part of the Dulaney Lot, a large land tract owned by attorney, Daniel Dulaney, before the Revolutionary War. 1 William Williams was the first owner and operator of the Ceresville Flour Mills, saw and grist mills. 2 In addition he owned a ferry that taxied passengers across the Monocacy River before the erection of the Monocacy Bridge.

The property was owned by a number of prominent citizens in the ensuing years. It was purchased by Samuel Hoke, Sr. in 1856 and thus became a possession of the Hoke family. 3 The home was lived in by Samuel Hoke, Jr. for a number of years and subsequently bought by him in 1871. 4 The house and lands remained in the Hoke family until 1891. 5

The Samuel Hoke House is a significant structure in Frederick County history. Historically the house has been associated with a number of prominent citizens. The house is significant architectureally as an excellent example of vernacular architecture. The structure is unique due to the extensive use of coursed quarried stone in the construction of the house, gate, fence, and outbuildings. The stone was quarried from the Ceresville Stone Quarry located on the premises. The house and outbuildings are a significant addition to the heritage of Frederick County architecture.

¹Frederick County Land Records, Liber W.R. 46; Folio 498.

²T.J.C. Williams, <u>History of Frederick County Maryland</u>, (1910; rpt. Baltimore: Regional Publishing Co., 1967), Vol. II, page 1353.

³Frederick County Land Records, Liber E.S. 8; Folio 349.

⁴Ibid., Liber C.M. 7; Folio 272.

⁵Ibid., Liber W.I.P. 13; Folio 480.

F-8.40

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Frederick County Land Records.

Williams, T.J.C., <u>History of Frederick County Maryland</u>, (1910; rpt. Baltimore: Regional Publishing Co., 1967) Vol. II, page 1353.

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA


ACREAGE OF NOMINATED PROPERTY 137 acres, 2 roods, and 8½ perches

VERBAL BOUNDARY DESCRIPTION		
LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING S	TATE OR COUNTY BOUNDA	ARIES
STATE COUNTY		
STATE COUNTY		
STATE		
CONV DRED ARED DV		
FORM PREPARED BY		
NAME / TITLE		c1h
Deborah Sheetenhelm, Intern		
ORGANIZATION	DATE	
Frederick County Office of Historic Preservation	9/19/79	
STREET & NUMBER	TELEPHONE	
12 East Church St., Winchester Hall	694-1063	
CITY OR TOWN	STATE	•
Frederick	Maryland	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438





Attachment 6 Photographs, Page 1

Samuel Hoke House (F-8-40) N.W. Corner and approach road



Hoke House East Elevation



Hoke House N.W. Corner



Hoke House East Elevation



Hoke Tenant House MD 26 at farm entrance



Garage (on site of mostly destroyed house) East Elevation



Attachment 6 Photographs, Page 3

Garage South Elevation



Summer Kitcher N.W. Corner



Quonset building (horse barn) west elevation; plus concrete block milking parlor



F-8-40 Samuel Hoke House northuest eleration DE5 7/21/79 3/5 Ronte 406 Cérville



F-8-40 Jamuel Hoke He Stone onthruldery west elevation DE5 7/07/79 3/5 Route 406 Ceraxelle